

Ticket Report

Organisation	Meiwu Technology Company Limited
Ticket UID	T/PDM/UAW/26/00023
Status	Assigned
DueDate	16-Mar-2026
Site	Gladeville
User Type	Employee
Department	NA
Reported By	Bex Pollak
Mobile Number	+91 2000004311
Others Involved	NA
Category	Unsafe Action - by workforce
Observation	mobile scaffolding without railing
Evidence	photo
Location	11th floor
Recommendation	Quality action taken

Ticket Image(s)



Ticket Video(s)	NA
Ticket Audio(s)	NA
Ticket File(s)	NA
Created	16-Mar-2026 12:05:27 PM
Modified	16-Mar-2026 01:28:20 PM
Investigation Checklist	NA
Assigned To	Leota Blackmore
Resolved On	NA

16-Mar-2026 12:05:27 PM - Bex Pollak: Uploaded 1 Attachment(s).

16-Mar-2026 12:05:27 PM - Bex Pollak: A new record was created:
Uid set to 'T/PDM/UAW/26/00023' Site set to 'ANSR Mizuho'
Reported By set to 'Aakash Kumar' Category set to 'Unsafe Action -
by workforce'

16-Mar-2026 01:28:20 PM - Bex Pollak: Quickly action taken

16-Mar-2026 01:28:20 PM - Bex Pollak: Ticket status updated to
Assigned. Assigned To has been updated to 'Rahul Singh' Due
Date has been updated to '16-Mar-2026'

Ticket History



To view all Audio(s)/Video(s)/Photo(s)/File(s), Visit:

<https://www.incidentreporter365.com/#/incidents/view/256/68258>

This is a computer generated report. For queries please mail to contact@oqsha.com