

Wood Cutter Checklist

 Ref No.: PI/EHS/C/43
 Issue date: 05/05/25
 Rev No: 00

Inspection Information

Name of Site/Location	Austin	Frequency	Weekly
Name Of Contractor	Universal ltd	Responsible for checks	SO
Date of First Deployment	01-Mar-2026	Checked by & date during site EHS Risk Evaluation	SO - Lakshman 25-Mar-2026
Date of Inspection	30-Mar-2026	Machine Serial No:	8248364WOOD

Checklist

Description	Yes	No	N/A	Remarks
1.Wheel guard is fixed properly - On operator's side	Yes			Wood Cutter Checklist
2.Cutting blade without any crack and mounting to be done with proper check nut.				Wood Cutter Checklist
3.Body is free from any damage.		No		
4.Presence of Cord strain reliever (glands).				
5.Trigger switch without damage.			N/A	
6.Presence of Spindle lock for change wheel.				
7.Cable condition (Any cut, wear etc) and presence of wire top plug with proper gland.				
8.Use industrial power plugs / sockets - Two pin for double insulated body / Three pin for metallic body.				

Overall Observation

Acceptable(Yes/No): Yes	If not acceptable - Equipment removed from site(Date) : NA	Corrective/Preventive action taken on (Date) : NA
--------------------------------	--	---

Inspection Team

Inspected by	Name	Date	Status
Contractor's Electrical	Hebert Eaton	20-Mar-2026 11:27:00 PM	Signed
Contractor's Site EHS Officer			Unsigned
PMC Site EHS			Unsigned

Inspection History

Created On	Created By	Comment	Attachments
------------	------------	---------	-------------