


# Fire Extinguisher Inspection Checklist

Ref No.: PI/EHS/C/29  
Issue date: 05/05/25  
Rev No: 00

### Inspection Information

<b>Name of Site/Location</b>	Austin	<b>Frequency</b>	Daily
<b>Name Of Contractor</b>	Universal	<b>Responsible for checks</b>	SO
<b>Date of First Deployment</b>	16-Mar-2026	<b>Checked by &amp; date during site EHS Risk Evaluation</b>	So - lakshman 23-Mar-2026
<b>Date of Inspection</b>	24-Mar-2026	<b>Machine Serial No:</b>	3286r823

### Inspection Type Attachment



### Checklist

Description	Yes	No	N/A	Observation Details
1.Condition of the extinguisher (Clean and Tidy)	Yes			Report - Fire Extinguisher Inspection Checklist
2.Physical appearance for corrosion.				
3.Safety pin in position		No		Report - Fire Extinguisher Inspection Checklist
4.Condition of discharge nozzle (any blockage/damage)				
5.Condition of hose(any leakage/broken)			N/A	Report - Fire Extinguisher Inspection Checklist
6.Availability of visual board.				
7.All the indicator gauges in working condition.				Report - Fire Extinguisher Inspection Checklist
8.Refill date of extinguisher is expired				
9.Cylinder weight verify (If the gross weight of the cylinder is reduced by 10% then cylinder need to be refilled).				
10. Identification number of extinguisher				
11.Location of extinguisher to be fixed				
12.All cylinders should be as per IS-15683-2006.				

### Overall Observation

<b>Acceptable (Yes/No):</b> N/A	If not acceptable - Equipment removed from site(Date) : 30-Mar-2026	Corrective/Preventive action taken on (Date) : 29-Mar-2026
---------------------------------	---	--

### Inspection Team

Inspected by	Name	Date	Status
Contractor's Supervisor			Unsigned
Site EHS Officer			Unsigned

### Inspection History

Created On	Created By	Comment	Attachments
------------	------------	---------	-------------